


TECH EXPERT™ SOLUTIONS


Tech Expert™ HID Headlight Ballast



The Problem: Despite their superiority to halogen headlights, HID Headlights can still fail, typically from overheating, moisture intrusion, damage from a frontal collision, or burning out from repeated duty cycles. If one of those scenarios occurs, it can cause the system to become inoperative, creating reduced visibility and safety concerns for drivers and motorists.

Our Response: To help restore proper lighting function to HID light systems, Tech Expert™ created OE-Exact Match HID Headlight Ballasts. That means they are direct-replacement parts that match the fit, form, and function of the originals. Plus, as DOT-certified parts, our HID Headlight Ballasts comply with Federal Motor Vehicle Safety Standards.

Heavy-duty casings around electronics ensure durability



Internal circuitry matches OE design to ensure performance

Plug-and-play design means no need for reprogramming

HID100
Cadillac Escalade (14-07)
Cadillac Escalade ESV (14-07)
Cadillac Escalade EXT (13-07)
VIO over 200,000

We believe premium quality should extend to aftermarket parts. That's why we created our OE-Exact Match HID Headlight Ballasts. Exceptional quality without sacrificing fit, form, and function.



Expert Solutions for Professional Technicians™

