



ECHLIN

DID YOU KNOW?


Cummins 5.9L Diesel Fuel Injector Kits

Solving the well-known Fuel Feed Tube Problem

Once installed, fuel feed tubes are not visible to technicians. If one or more of the tubes seats improperly due to wear, a tech may incorrectly assume the injector is malfunctioning; when the real issue could be fuel leaking back to the fuel return line from the tube itself.

To ensure a proper installation, NAPA® Echlin® recommends replacing the fuel feed tube every time an injector is replaced. This step helps technicians to do the job right and prevent misdiagnosed injector problems.

“ The new Diesel Fuel Injector Kit includes a precision-remanufactured NAPA® Echlin® diesel injector, NEW fuel feed tube, fuel & tank contamination testing kit, and full-color detailed installation instructions.



INJ335RK

Dodge Cummins Engines (2009-04)
5-Hole Injector Nozzle

INJ326RK

Dodge Cummins Engines (2004-02)
8-Hole Injector Nozzle




ECHLIN

DID YOU KNOW?

NAPA® Echlin® Fuel Feed Tubes are 100% New and Undergo a 2-Step Cleaning Process


Even though, all NAPA® Echlin® Fuel Injector Sleeves are 100% NEW we put them through a 2-step ultrasonic cleaning process to ensure they are contaminant-free. O-rings are installed in our clean room and the tube is packed in an individually sealed bag. These extra steps ensure trouble-free operation and a long service life.



Tech Tip: Installing the Right Injector


INJ335R

5-Hole Injector Nozzle



INJ326R

8-Hole Injector Nozzle



Installing the incorrect fuel injector on 2004 Dodge Cummins engines is a common error. **Although the fuel injectors appear to be the same, they are not interchangeable. The NAPA® Echlin® INJ326R injector is designed with an 8-port injector nozzle and INJ335R features a 5-port injector nozzle.**

Watch the NAPA® Echlin® ‘**Dodge Cummins Fuel Injector Sleeve Tips & Best Practices**’ video for installation assistance.



LOOKS RIGHT. FITS RIGHT. PERFORMS RIGHT.

NAPAEchlin.com

NE10235D_5.9FJK